

Kühlung Büffet-Element

Artikel-Nr. 651071 (9BTIS5NNHCA90 / SERVICE PURPLE C Anfahrelement
RISCALD)

Explosionszeichnung / Ersatzteile

Bitte bei Ersatzteilbestellung immer Artikelnummer und Seriennummer
mit angeben!


Cod. ESP384

Denominazione: SERVICE PURPLE INSERIMENTO HOT

Data: 07/05/13

INDICE DI MODIFICA: 00

	PARAM.	OPTIONAL
⚡	SCE001	OPT
	TAR001	



Code	Description	Notes
74702120	FIXES GLASS	
72538626	SUPERSTRUCTURE TOP GLASS	
72538776	FRONTAL GLASS	
74742017	LIGHT ON/OFF SWITCH	2
74742192	SOCKET	
74741636	HOLDERLAMP	2
72539086	LED LIGHTING COVERING	
72557114	GLASS SUPPORT	
72539674	FRAME FIXING KIT	
72591904	LAMP PROTECTION	
74702072	HOOK	
74751010	HALOGEN LAMP	1
73669056	SUPERSTRUCTURE	
72539070	SUPERSTRUCTURE SIDE SUPPORT	
72539682	SIDE FRAME	
72539696	FRONT BOTTOM FRAME	
72546854	FOOD ISLAND TOP LONGER SIDE PANEL	
72546794	FOOD ISLAND TOP SIDE PANEL	
72545794	EXTERNAL BOTTOM SIDE PANEL	
72547204	INTERNAL BOTTOM SIDE PANEL	
72547214	LOW BACK PANNEL	
72547174	INTERNAL UP SIDE PANNEL	
72547164	INTERNAL UP SIDE PANNEL	
72547194	UP RIGHT SIDE	
72547184	UP LEFT SIDE	
74708007	CASTOR/FEET	