



Spülen & Hygiene Geschirrspüler

Artikel-Nr. 812005, 812006, 812007, 812008, 812009, 812010
(GS50R, GS51R, GS50AP+R, GS51AP+R, GS50AP+R+E, GS51AP+R+E)

Explosionszeichnung





**SPARE PARTS CATALOGUE
ERSATZTEILKATALOG
CATALOGUE PIECES DETACHEES
CATALOGO PARTI RICAMBIO
CATALOGO DE PIEZAS DE RECAMBIO
CATALOGO PEÇAS DE REPOSIÇÃO**


GSP50


GSP51



02-03-2009




















B. 237

130109 (230V- 50Hz)



T. 173

