


DOMINATOR PLUS



ITEM No	BIN No	DESCRIPTION	7Kw	10Kw	SPARES No.
1	P613150	INDUCTION HOB ASSY		Y	734070000
2	R6447	MCB - 13A 3P TYPE-D	Y	N	734070001
	R6443	MCB - 20A 3P TYPE-D	N	Y	734070002
3	TBA	270mm RND INDUCTION COIL 3.5KW	Y	N	TBA
	R5967	270mm RND INDUCTION COIL 5KW	N	Y	73420002
4	R6433	7Kw INTRO Q TWIN ZONE 270 RND COILS	Y	N	734070003
	R6437	10Kw INTRO Q TWIN ZONE 270 RND COILS	N	Y	734070004
5	R5920	CONTROLS ASSY		Y	734250005
6	R6375	E3904I COIL CONTROL KNOB 6.0mm		Y	734060003
7	R5919	EGO GREEN INDICATOR		Y	734250006
8	R6441	FILTER TWIN ZONE		Y	734070005
22		Inner Side Stiffening Bracket			



Issue	Alteration	Date	Product	Document Reference
A	Initial Issue	09/08/11	E3901i/E3902i	AD49334