



## Kühlung Büffet-Element

Artikel-Nr. 651062 (9BESS4CEFWA16 / SERVICE BROWN 4W)

---

### Explosionszeichnung / Ersatzteile

---

Bitte bei Ersatzteilbestellung immer Artikelnummer und Seriennummer mit angeben!


Cod. ESP380

Denominazione: SERVICE BROWN

Data: 03/05/13

INDICE DI MODIFICA: 00

	PARAM.	OPTIONAL
⚡		
	SCE001	TAR001
		OPT



<b>Code</b>	<b>Description</b>	<b>Notes</b>
74702120	FIXES GLASS	
72538784	SUPERSTRUCTURE TOP GLASS	
74776684	TEMPERED GLASS	
72538774	FRONTAL GLASS	
74742008	MAIN ON/OFF SWITCH	2
74742017	LIGHT ON/OFF SWITCH	2
75956088	POWER RELAY	2
74741636	HOLDERLAMP	2
72539084	LED LIGHTING COVERING	
72557114	GLASS SUPPORT	
72539674	FRAME FIXING KIT	
72591904	LAMP PROTECTION	
74702072	HOOK	
74751010	HALOGEN LAMP	1
73669454	SUPERSTRUCTURE	
72539070	SUPERSTRUCTURE SIDE SUPPORT	
72539680	SIDE FRAME	
72539694	FRONT BOTTOM FRAME	
72546356	FOOD ISLAND TOP LONGER SIDE PANEL	
72546306	FOOD ISLAND TOP SIDE PANEL	
72546316	EXTERNAL BOTTOM SIDE PANEL	
72546326	INTERNAL BOTTOM SIDE PANEL	
72546406	BOTTOM SHELF	
72545666	LOW BACK PANNEL	
70259094	HEATING ELEMENT	2
SC852	ELECTRICAL WIRING	1
RIF.TAR.B03	CONTROLLER PRESETTING SERVICE	1
74700897	UNSETTED ELECTRONIC CONTROLLER	1
74700899	PROBE	1
74708007	CASTOR/FEET	
73669842	POWER BOX	